Corner I.D. # 110T

MONUMENT RECORD

STATE OF INDIANA ~ COUNTY OF MONROE

8/31/2016, Rachel Savic Monument recovered in 4/6/2018, Rachel Savich	h Oser, Fbk. 48, pg. 7 good condition, flush Oser, Fbk.51, pg. 62 good condition, flush	Recovery '	rie Drawing -post w' MCSO sign 1.1' eas		•
	South bound	S.R.37 North bound	Conc. Ditch Smithville Road		1
			·· ».		N I.T.S. um Monument r = •
State Plane Coording Northing: 139	ate (NAD83 Surve	y Feet, Indiana We Easting:	st Zone)- 3108202.64	Elev.:	796.7

in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; this 9th day of June, 2004 A.D.

Indiana Registered Land Surveyor No. LS20200079



ImageSource: 2014 Monroe County Pictometry



2004 Geodetic Control Project
119 West 7th Street
Bloomington, Indiana 47404
(812) 349-2570





